



Levels 2, 3 and 4 as viewed from the northwest.



East wing Level 4 high roof.



Window installation along level 3 at Grid V1



Excavation for concrete trench backfill within La Jolla Shores Drive



Placement of concrete cap for trench repair within La Jolla Shores Dr.



Level 4 exterior framing along Line V1.



Level 4 framing along grid line W8.



Setting reinforcing steel on Level 4 wall at Line 8.8.





Southwest elevation of the building as seen from La Jolla Shores Drive.



Level 4 west roof showing 'ponding' on roof.



Level 4 sheathing along Line 1.



Level 4 sheathing, treated nailers and roofing along Line W5.



Level 1 generator pad reinforcement prior to placement of concrete.



Level 1 generator pad after placement of concrete.



Level 4 wall forms along Line J and 9.1.



Installation of 12" waterline within La Jolla Shores Drive.





Testing of Level 2 windows along Line V1.



Testing of Level 2 windows along Line V1.



Testing of Level 2 windows along Line V1.



Sheathing and stainless steel shade support on Level 4 at Line V1.